
City of Lindsay 608 Ash Street, PO Box 153 Lindsay, Texas 76250



8229



Account Number: 1256-3178-258607	
Date:	10/1/2022
Property Location:	Mike's Burrito and Burger 319 J M Lindsay Blvd Lindsay, TX 76250

City of Lindsay - Notice of Backflow Prevention Assembly Test Expiration

Dear Customer,

Our records indicate that you have not completed a test on one or more Backflow Prevention Assemblies installed in your water service, within your plumbing system, or within your irrigation system by the required Expiration Date indicated below. We must receive an acceptable test report to indicate that the backflow prevention assembly is in working order.

The test results must be completed by a registered Backflow Prevention Assembly Tester (BPAT) and the results submitted through our online system no later than 10/31/2022.

For a list of registered and approved Backflow Prevention Assembly Testers, please visit our website at https://lindsay.texas.gov/cross-connection-control-backflow/.

If any backflow assembly has been tested within the past twelve months, the assembly is no longer in service, or there are any other discrepancies in the information provided in this letter, please let us know so that we may correct our records.

Note: Backflow prevention assemblies on fire protection sprinkler systems are required by the State Fire Marshal to be tested and/or repaired by a BPAT who is a full-time employee of a fire protection sprinkler company that is licensed with the State Fire Marshal's Office.

Should you have any questions, please write or call:

City of Lindsay Monica Laux 608 Ash Street, PO Box 153 Lindsay, Texas 76250

Telephone: 940-665-4455

Email: cityoflindsay@ntin.net

Your prompt attention to this matter would be greatly appreciated.

Sincerely,

Monica Laux

Assembly Information	Location Description	Last Tested By	Expiration Date
Watts LF009QT 1/2 - RP	Soda fountain		Tested On: 9/8/2021
SN: 260676			Expiration: 9/8/2022